

Project: Alaska Copper	Works	in	Inspection Date: 2/26/19			
Project No.: 18ACW1			Technician:	David DuBois		
System Performance:						
Was system running during the	inspection? \square Yes	⊠ No				
Flow Rates (gpm)	Influent <u>n/a</u>	Effluentn/	a The flows sh	nould be ~155 gpm		
Bag Filter #1 Pressures (psi)	Influentn/a	Effluentn/		ers should be replaced al pressure > 8 psi		
Bag Filter #2 Pressures (psi)	Influent <u>n/a</u>	Effluentn/				
Carbon Filter Pressures (Lead)	Influent <u>n/a</u>	Effluentn/		The carbon filters should be backflushed if differential		
Carbon Filter Pressures (Lag)	Influent <u>n/a</u>	Effluentn/				
Were the bag filters replaced?	☐ Yes 区 No					
Was the carbon backflushed?	☐ Yes 🗵 No					

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	Issues/Notes/Comments		
Walchem Controller Inspected	⊠ Yes □ No	Display operable, no flow due to freeze protection		
Flow Meters Inspected	⊠ Yes □ No			
Level Sensor Cleaning/Inspection	☐ Yes ☒ No			
Inspect System Plumbing	ĭ Yes ☐ No			
Pumps Inspected	⊠ Yes □ No	Pump drained		
General Housekeeping	☑ Yes ☐ No			
Chemistry Level	☑ Yes ☐ No	1.5 drums onsite		
Safety Materials Inspected	☑ Yes ☐ No	Additional PPE and safety equipment stored in a satellite storage container outside of chemical storage on 2/27/19		
pH Probe Inspection/Calibration	□ Yes 図 No	Inline tank probe placed outside of tank and lines are drained		



Water Sampling:								
Were water samples ta	ken? 🔲 Yes	⊠ No						
Raw water:	pH <u>n/a</u>	Turbidity _	n/a	NTU				
Bag Filter Influent	pH <u>n/a</u>	Turbidity _	n/a	NTU				
Bag Filter Effluent	pH <u>n/a</u>	Turbidity	n/a	NTU				
Carbon Filter Influent	pH <u>n/a</u>	Turbidity	n/a	NTU				
Carbon Filter Effluent	pH <u>n/a</u>	Turbidity	n/a	NTU				
Monthly Tasks:								
Were samples submitted to Analytical? ☐ Yes ☒ No								
Analytical Lab:								
Was Walchem data dov	wnloaded?	□ Yes 図 No						
Were the tank sludge levels checked? ☑ Yes ☐ No								
Sludge Depth (inches):								
Decant Tank: 0								
Treatment tank:0								
Backflush tank: 0	**************************************							
Main lift station:								
North lift station:								
South lift station:	***							
Additional Comments, Recommendations and System Upsets:								
Recommended to install a rise in the discharge pipe to allow the flowmeter to be fully								
submerged at all tin	nes.							
David DuBois	5	Project Lea	ad Te	ch	2/28/19			
Technician		Title	?		Date			

Submit Page 2 of 2